

JAE Oregon, Inc.	Supplier Quality Manual	RQAM-0002DS-01		
Title: Barcode Label Guidelines	Original Issued: 05/23/2008	Rev	Date	CN
		A	05/23/08	N/A
	Originating Department: Information Technologies	B	10/21/08	080730

Printed Document is UNCONTROLLED



BARCODE LABEL

GUIDELINES

REVISION 1

← 6 inches (+/- .05) →

MATERIAL CONTROL LABEL			
ITEM DESCRIPTION: INS, MX41-PC			
ITEM NO. (M) C273-50136=R0			
P.O.# (O) 410013505	P.O. Line # (N) 1		
QTY. (Q) 40000	UM. (U) EA	VENDOR NUMBER	
		SAP Vendor No.	
MAT'L LOT NO. (L) 120-57139		MANUFACTURER PART #	
		ABC123-567DEF	
RAMS/DRAWING # rams/drawing #		MFG DATE 3/12/08	
VERIFIED BY			

↑ 4 inches (+/- .05) ↓

JAE Oregon, Inc.	No. RQAM-0002DS-01B	Page 3 of 3
------------------	---------------------	-------------

Material Control label Specifications

1.1 ITEM DESCRIPTION

This is the JAE OREGON item description.

1.2 ITEM NO.

This is the JAE OREGON item number.

Barcode: This will have a barcode qualifier of “M”.

1.3 P.O.

This will reference the purchase order number.

Barcode: This will have a barcode qualifier of “O”.

1.4 P.O. Line

This will reference the line number on the purchase for this item.

Barcode: This will have a barcode qualifier of “N”.

1.5 QTY.

This will be the quantity in a measurement represented by the unit of measure.

Barcode: This will have a barcode qualifier of “Q”.

1.6 UOM

This is the unit of measure specified by JAE OREGON.

Barcode: This will have a barcode qualifier of “U”

1.7 VENDOR NUMBER

This is the SAP Vendor No. as specified by JAE OREGON.

1.8 MAT'L LOT NO.

This is the material lot number as specified by the supplier.

Barcode: This will have a barcode qualifier of “L”.

1.9 MANUFACTURER PART

This is the manufacturer part number as specified by the supplier.

1.10 RAMS/DRAWING

1.11 MFG DATE

This is the date the product was manufactured in a mm/dd/yy format.

1.12 VERIFIED BY

This section is to be left blank for use by JAE OREGON only.